



# CREATING A 3D PART USING INVENTOR SOFTWARE



## **STAGE 3**

Finish the sketch then use the extrude command to achieve the required distance



## **STAGE 4**

Create a new sketch on the top surface as shown above.