



CREATING A 3D PART USING INVENTOR SOFTWARE



STAGE 7

Finish sketch then cut all the way through the model.

Using the extrusion cut tool



STAGE 8

Complete you model by giving it a texture finish